



STORM SUMMARY 3-7-18

The main concern for the morning commute on 3-7 was the possibility for wet roads from the previous day icing up for the morning commute. Salting as a preventative measure to prevent the refreeze from occurring was preformed. Surfaces as of 2-3am were still moist across the areas but as air temperatures were slipping into the 20s and pavement temps were falling surfaces did officially ice up. Brisk and gusty northwest winds 15-25 mph with some gusts near 30 prior to dawn caused these wet areas to really slick up. There were some lingering flurries till 2am.

VIP Property Maintenance 847-760-5080/Tecza Landscape Group 847-742-3320